

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5					
6	7.5				Y
7					
8					
9					
10					
11					
12					
13	7.5				Y
14					
15					
16					
17					
18					
19					
20	7.5				Y
21					
22					
23					
24					
25					
26					
27	7.5				Y
28					
29					
30					
31					
No = 1	lo = N = Excursion) Total N's				

< <have< th=""><th>County: Marion Agency: MARIO</th><th>ON COUNTY</th></have<>	County: Marion Agency: MARIO	ON COUNTY				
minimums	ENTRY POINT					
been met for this day?	EP-A					
PWS ID 4101464						
Hidden Meadows Water Assoc						
Sample pe	riod: November 2	.021				
	 Month/Year					

Number of excursions during this month: $\underline{0}$

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference					
Minimum Water Quality Parameter(s) as set by State:					
pH 7.2					

Print Name: Matt	Matt Olson					
Signature:	Medt Elsen					
Date & Phone#:_	12-09-2021	503-438-0471				
Send to DWP within 10 days after end of sampling period						

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/